


REV	DESCRIPTION	DATE
A	RELEASE	1/7/09

- NOTES:
- 1

APPLY ANTI-SEIZE LUBRICANT P/N: 508183 TO OUTSIDE OF PULLER AND INSIDE OF ANVIL
- 2

APPLY LOCTITE 242 P/N: 505016 TO THESE THREADED JOINTS PER MFR'S INSTRUCTIONS.
- 3

APPLY WARNING STICKER P/N: 590273 TO ANVIL HOLDER. DO NOT PERMIT STICKER TO OVERLAP ONTO ANVIL.



129100	1	PULLER	3
129099	1	ANVIL HOLDER	2
129004	1	ANVIL ASSEMBLY	1
PART NO.	QTY	DESCRIPTION	ITEM

HUCK INTERNATIONAL, INC., I.S.D.
1 CORPORATE DR, P.O. BOX 2270
KINGSTON, NEW YORK 12401

NOSE ASSEMBLY 1/2" BOBTAIL
2620 TOOL

DET: trk CK: DATE: 1/7/09 SCALE: 1:1

FOC.
FAC.

B

99-7845